


TABRIZ
ILS RWY 30L
CAT A/B/C/D



MISSED APPROACH: At 0.8 DME FM ITBL climb straight to TBZ DVOR/DME, then turn left climb on RDL 285 to 7500 FT, then turn left to cross overhead DVOR/DME, then intercept RDL 082 to rejoin HLDG at 12000 FT.

THR RWY 30L ELEV. 4441 FT

1-Circling not authorized between RDL 355 and RDL 102 clockwise direction for ACFT CAT C/D .
2-Missed APCH procedure Penetrates OIA42.
3-Contour intervals are to be selected at 990 FT.

OCA(H)		A	B	C	D
Straight-in Approach	CAT I	4750' (309')			
	LOC (GP INOP)				
Circling		5980' (1531')			