
STANDARD DEPARTURE CHART-INSTRUMENT (SID)-ICAO

DEZFUL/DEZFUL RWY 32L/R DAPEM 1A, DARON 1A DAPIK 1A



DAPEM 1A DEP:

DEP RWY 32R/L - After take off maintain RWY heading, cross 15 DME at or above 4000 FT, then turn right heading 075°, cross R359 at or above 5000 FT, then intercept RDL 027 to DAPEM, cross 25 DME at or above FL100, then climb to cleared level.

DARON 1A DEP:

DEP RWY 32R/L — After take off maintain RWY heading to intercept and maintain 8 DME arc to the left, cross R190 at or above FL60, after crossing R165 maintain heading 075° to intercept R120 to DARON then climb to cleared level.

DAPIK 1A DEP:

DEP RWY 32R/L - After take off maintain RWY heading, cross 15 DME at or above 4000 FT, then turn right heading 045° to intercept R359 to DAPIK, cross 25 DME at or above FL100, then climb to cleared level.